



## 202 E. Hillside Avenue - Contributing

At this location is a one-and a half story, modified gabled ell Folk dwelling built ca. 1886 and extensively remodeled ca. 1930. The house has a steeply pitched gable roof of asphalt shingles, an added concrete block foundation and an exterior of weatherboard siding. On the south elevation is a partial-width shed roof porch that was enclosed ca. 1930-40. The porch has one-over-one double hung wood sash windows, a single-light glass and wood door and a weatherboard exterior. At the roofline of this elevation is a gable roof dormer with one, one-over-one double hung wood sash window. On the east elevation is a gable roof dormer with a multi-light diamond-shaped window. On the west elevation is a small inset entry porch with chamfered wood posts which are connected by a small wooden valence with a central arrow-and-dart drop pendant and clover leaf cutouts. The porch railing has milled balusters. The main entrance is located on this elevation and has a ca. 1970, glass and wood door with louvered glass. The windows on the dwelling are primarily original two-over-two wood sash.

At the roofline of the west elevation is a gable roof dormer with paired, two-over-two double hung wood sash windows. In the dormer's gable field are wood shingles of various patterns and a central diamond shaped attic window. On the north elevation are two, original gable roof wings. The westernmost wing has a small shed roof porch on its east elevation with chamfered wood posts. This wing also has a diamond-shaped attic window on its north elevation. There are two, small one-over-one double hung wood sash windows on the west elevation. The house has an interior brick chimney that appears to be rebuilt.



## 202 E. Hillside Avenue- continued

Associated with the dwelling is a frame garage ca. 1930. The garage has a hipped roof of asphalt shingles, a poured concrete foundation and a shiplap exterior. On the west elevation are two garage bays with double, six-light and three-vertical panel hinged doors. A pedestrian door on the south elevation has a flush wood door. The windows in the garage are fixed, six-light windows. **-Contributing**

